

# U.S. ENVIRONMENTAL PROTECTION AGENCY POLLUTION REPORT

#### I. HEADING

Date: November 3, 1997

Subject: Durako Paint, Detroit, Wayne County, Michigan From: Dave Anderson, OSC, U.S. EPA, RS1, Grosse Ile,

Michigan

 $T \circ :$ 

P. Nadeau Attn: K. Mould, USEPA, OSWER, Wash.D.C (VIA LAN)
R. Karl, Chief, ERD, Chicago, IL(VIA LAN)
B. Messenger, Chief, ESS, Chicago, IL(VIA LAN)
M. Bensing, ESS, Chicago, IL(VIA LAN)
J. El-Zein, Chief, RS1, Grosse Ile, MI(VIA LAN)
B. Beauchamp, ORC, Chicago, IL(VIA LAN)
T. Lesser, OPA, Chicago, IL(VIA LAN)
C. Allen, OPA, Chicago, IL(VIA LAN)
R. Spaulding, MDEQ, Livonia, MI(E-MAIL)
S. Lile, Dept of Env, Detroit, MI (FAX: 313-224-1547)
Duty Officer, NRC, Washington D.C(E-MAIL)
D. Henne, Department of Interior(E-MAIL)
Lt. J. Flynn, USCG AST, Fort Dix, NJ(E-MAIL)

POLREP No.: POLREP 2

# II. BACKGROUND

Site No.: B510
Response Authority: CERCLA

CERCLIS No.: MID 005 326 673

NPL Status: No

Start Date: October 14, 1997

Demobilization Date: N/A Completion Date: N/A

# III. SITE INFORMATION

A. <u>Incident Category</u> Time Critical Removal Action at an inactive paint production facility.

# B. Site Description and Location

1 Site location

The Durako Paint site, a former paint manufacturing facility, is located at 6315 East 7 Mile Road, Detroit, Wayne County, Michigan (42°26'1.7" North, 83°2'19.8" West). The site consists of two properties. The first property, located at 6315 East 7 Mile Road is approximately 21,000 square feet in area (210 feet by 100 feet).

The second property, located approximately 250 feet north of the building property, is situated on the east side of Filer Street. Both parcels of the site are located in a mixed industrial/residential area of Detroit.

Please refer to the initial POLREP for more detailed information.

#### IV. RESPONSE INFORMATION

# A. Situation

#### 1. Current situation

Approximately 780 waste drums have been staged on site. Documentation, sample collection, and hazcatting is being conducted. Disposal arrangements have been initiated for waste drums.

#### 2. Removal activities to date

On 10-27-97, sampling of drums continues, to be used for hazcatting and disposal purposes.

On 10-28-97, sampling of drums continues. Drums are moved in the building to the staging areas inside and outside of the building. Triple-stacked drums are broken down and staged.

On 10-29-97, triple-stacked drums continue to be broken down and staged in the building. Drum numbering is initiated.

On 10-30-97, debris from the yard area is cleared. Staged drums are sampled for hazcatting and disposal purposes.

On 10-31-97, staged drums are sampled for hazcatting and disposal purposes.

On 11-1-97, staged drums are sampled for hazcatting and disposal purposes.

On 11-2-97, hazcatting of waste samples continues.

# B. Planned Removal Activities and Next Steps

- 1. Continue staging and sampling drums for enforcement documentation and hazcatting.
- 2. Begin waste disposal profiling and bid process.
- 3. Initiate transportation and disposal of waste drums.

# C. <u>Key Issues</u>

Arrangements have been made to have 40 drums of usable paint product shipped back to it's manufacturer. Dupont will pick up the drums of "Silver-Met" on November 4, 1997. The drums were inspected on site to insure that the material was the product as claimed.

#### V. COST INFORMATION

Costs as of 11-1-97.

	Budgeted		<u>5</u>	<u>Spent</u>		Remaining	
U.S. EPA DIRECT INDIRECT	\$	47,520 93,600	\$ \$	4,193.04 9,084.91	\$ \$	43,326.96 84,515.09	
START ERCS USCG	\$ \$ \$	160,000 900,000 60,000	\$12	8,973.43 29,214.18 6,854.50	\$ \$ \$	151,026.57 770,785.82 53,145.50	
	<del>\$</del> 1	,261,120	<del></del> \$15	58,320.06	<del></del> \$1	,102,799.94	

Percent of project funds remaining = 87.4%

NOTE: The above accounting of expenditures is an estimate based on figures known to the OSC at the time this report was written. The OSC does not necessarily receive specific figures on final payments made to any contractor(s). Other financial data, which the OSC must rely upon, may not be entirely up-to-date. The cost

accounting provided in this report does not necessarily represent an exact monetary figure which the government may include in any claim for cost recovery.

# VI. DISPOSITION OF WASTES

To date, 210 cubic yards (7 roll-off boxes) of non-hazardous debris have been shipped to the Arbor Hills Landfill in Northville, Michigan for disposal.